Floor Mount Installation Guide

Included Hardware:

- (1) Floor plate
- (4) 3/8"-16 x 3" anchor bolts
- (4) 3/8" Flat washers
- (4) 5/8" Hex screws
- (4) Leveling screws

Recommended Tools:

- 9/16” Socket driver and box wrench
- 3/8” Socket driver or box wrench
- 3/8” Drill Bit 4” inches or longer
- Drill and impact driver
- Concrete Drill

Step 1:

- Align the floor mount plate over the installation holes on the Industrial Portal
- Predrill the holes in the concrete floor using a 3/8” drill bit
- If the surface of the floor is unlevel, utilize the 4 leveling screws to create a level surface
- Install the (4) 3/8”- 16x 3” concrete anchors with 9/16” socket

Step 2:

- Remove the back panel from Industrial Portal with 3/8” wrench
- Align the installation holes on the Industrial Portal over the floor plate

Step 3:

- Install the (4) 5/8” Long 3/8”- 16 screws with washers as shown with a 9/16” socket to fasten the Industrial Portal to mount

Step 4:

- Ensure the Industrial Portal is securely fastened and stable before adding other hardware or stacking another Industrial Portal